ET6 and ET40 Status

1.ETagger6m

Allignments of T0 for TE and channels responses

Special data taking with ST91 and ST96 Data ST96 - contamination by off momentum positrons. Allignment withing about 15%

Calibration

Offline, ST91 data, PD CC are fixed Geometrical cuts, Correlation plot Calibration is done for 2002 Next steps - to tune HV according to offline calibration LED monitoring system. Zener diodes in biases

Online histos

Dependent on trigger mix Calibration coefficients - roughly from allignment MIddle of December - problem with T0 for ADC6 : SAMPL3_0 -> SAMPL1_0 2003 - unstable(??) behaviour of both ADC6 and ADC7 Can be corrected using LNEF bank (V.Andreev).

ET6 and ET40 Status

2.ETagger40m

Readout

Needs T0 tuning

Calibration


Procedure to be elaborated

Recent problems

Water leak Roof over detector to protect against water

Radiation damages of crystals To dimimish probability of radiation damage: install ET40 right before HERA will start LUMI RUN remove ET40 from beam plane during injection and rapming

DQM 28.05.03 Yu.Soloviev



ET40 damages